# Curves and Surfaces

Parametric Representations
Cubic Polynomial Forms
Hermite Curves
Bezier Curves and Surfaces
[Angel 10.1-10.6]

#### Goals

- How do we draw surfaces?
  - Approximate with polygons
  - Draw polygons
- How do we specify a surface?
  - Explicit, implicit, parametric
- How do we approximate a surface?
  - Interpolation (use only points)
  - Hermite (use points and tangents)
  - Bezier (use points, and more points for tangents)


# **Explicit Representation**


- Curve in 2D: y = f(x)
- Curve in 3D: y = f(x), z = g(x)
- Surface in 3D: z = f(x,y)
- Problems:

  - How about a vertical line x = c as y = f(x)? Circle  $y = \pm (r^2 x^2)^{1/2}$  two or zero values for x
- Too dependent on coordinate system
- Rarely used in computer graphics

# Implicit Representation

- Curve in 2D: f(x,y) = 0
  - Line: ax + by + c = 0
  - Circle:  $x^2 + y^2 r^2 = 0$
- Surface in 3d: f(x,y,z) = 0
  - Plane: ax + by + cz + d = 0
  - Sphere:  $x^2 + y^2 + z^2 r^2 = 0$
- f(x,y,z) can describe 3D object:
  - Inside: f(x,y,z) < 0
  - Surface: f(x,y,z) = 0
  - Outside: f(x,y,z) > 0







# Constructive Solid Geometry (CSG)


Generate complex shapes with basic building blocks

machine an object - saw parts off, drill holes glue pieces together


This is sensible for objects that are actually made that way (human-made, particularly machined objects)
















#### The Six Platonic Solids

(by Jim Arvo and Dave Kirk, from their '87 SIGGRAPH paper Fast Ray Tracing by Ray Classification.)

#### See

http://www.sjbaker.org/teapot/
for more history.



# Algebraic Surfaces

- Special case of implicit representation
- f(x,y,z) is polynomial in x, y, z
- Quadrics: degree of polynomial ≤ 2
- Render more efficiently than arbitrary surfaces
- Implicit form often used in computer graphics
- How do we represent curves implicitly?

#### Parametric Form for Curves

- Curves: single parameter u (e.g. time)
- x = x(u), y = y(u), z = z(u)
- Circle: x = cos(u), y = sin(u), z = 0
- Tangent described by derivative

$$\mathbf{p}(u) = \begin{bmatrix} x(u) \\ y(u) \\ z(u) \end{bmatrix} \qquad \frac{d\mathbf{p}(u)}{du} = \begin{bmatrix} \frac{dx(u)}{du} \\ \frac{dy(u)}{du} \\ \frac{dz(u)}{du} \end{bmatrix}$$

• Magnitude is "velocity"


#### Parametric Form for Surfaces


- Use parameters u and v
- x = x(u,v), y = y(u,v), z = z(u,v)
- Describes surface as both u and v vary
- Partial derivatives describe tangent plane at each point p(u,v) = [x(u,v) y(u,v) z(u,v)]<sup>T</sup>

$$\frac{\partial \mathbf{p}(u,v)}{\partial u} = \begin{bmatrix} \frac{\partial x(u,v)}{\partial u} \\ \frac{\partial y(u,v)}{\partial u} \\ \frac{\partial z(u,v)}{\partial u} \end{bmatrix} \quad \frac{\partial \mathbf{p}(u,v)}{\partial v} = \begin{bmatrix} \frac{\partial x(u,v)}{\partial v} \\ \frac{\partial y(u,v)}{\partial v} \\ \frac{\partial z(u,v)}{\partial v} \end{bmatrix}$$

#### Assessment of Parametric Forms

- Parameters often have natural meaning
- Easy to define and calculate
  - Tangent and normal
  - Curves segments (for example,  $0 \le u \le 1$ )
  - Surface patches (for example,  $0 \le u, v \le 1$ )





## Parametric Polynomial Curves

- Restrict x(u), y(u), z(u) to be polynomial in u
- Fix degree n  $\mathbf{p}(u) = \sum_{k=0}^{n} \mathbf{c}_k u^k$
- Each c<sub>k</sub> is a column vector

$$\mathbf{c}_k = \left[ \begin{array}{c} c_{xk} \\ c_{yk} \\ c_{zk} \end{array} \right]$$

# Parametric Polynomial Surfaces


• Restrict x(u,v), y(u,v), z(u,v) to be polynomial of fixed degree n


$$\mathbf{p}(u,v) = \begin{bmatrix} x(u,v) \\ y(u,v) \\ z(u,v) \end{bmatrix} = \sum_{i=0}^{n} \sum_{k=0}^{n} \mathbf{c}_{ik} u^{i} v^{k}$$

- Each  $c_{ik}$  is a 3-element column vector Restrict to simple case where  $0 \le u,v \le 1$

# **Approximating Surfaces**

- Use parametric polynomial surfaces
- Important concepts:
  - Join points for segments and patches
  - Control points to interpolate
  - Tangents and smoothness
  - Blending functions to describe interpolation
- First curves, then surfaces





# Outline

- Parametric Representations
- Cubic Polynomial Forms
- Hermite Curves
- Bezier Curves and Surfaces

## **Cubic Polynomial Form**

- Degree 3 appears to be a useful compromise
- Curves:

$$p(u) = c_0 + c_1 u + c_2 u^2 + c_3 u^3 = \sum_{k=0}^{3} c_k u^k$$

- Each  $c_k$  is a column vector  $[c_{kx} \ c_{ky} \ c_{kz}]^T$
- From control information (points, tangents) derive 12 values  $c_{kx},\,c_{ky},\,c_{kz}$  for  $0\leq k\leq 3$
- These determine cubic polynomial form

## Interpolation by Cubic Polynomials

- Simplest case, although rarely used
- Curves:
  - Given 4 control points p<sub>0</sub>, p<sub>1</sub>, p<sub>2</sub>, p<sub>3</sub>
  - All should lie on curve: 12 conditions, 12 unknowns
- Space  $0 \le u \le 1$  evenly

$$p_0 = p(0), p_1 = p(1/3), p_2 = p(2/3), p_3 = p(1)$$

# Equations to Determine ck

• Plug in values for u = 0, 1/3, 2/3, 1

$$\begin{split} p_0 &= p(0) = c_0 \\ p_1 &= p(\frac{1}{3}) = c_0 + \frac{1}{3}c_1 + (\frac{1}{3})^2c_2 + (\frac{1}{3})^3c_3 \\ p_2 &= p(\frac{2}{3}) = c_0 + \frac{2}{3}c_1 + (\frac{2}{3})^2c_2 + (\frac{2}{3})^3c_3 \\ p_3 &= p(1) = c_0 + c_1 + c_2 + c_3 \\ \begin{bmatrix} p_0 \\ p_1 \\ p_2 \\ p_3 \end{bmatrix} = \begin{bmatrix} 1 & 0 & 0 & 0 \\ 1 & \frac{1}{3} & (\frac{1}{3})^2 & (\frac{1}{3})^3 \\ 1 & 2 & (\frac{2}{3})^2 & (\frac{2}{3})^3 \\ 1 & 1 & 1 & 1 \end{bmatrix} \begin{bmatrix} c_0 \\ c_1 \\ c_2 \\ c_3 \end{bmatrix} \quad \begin{array}{c} \text{Note:} \\ p_k \text{ and } c_k \\ \text{are vectors!} \\ \end{array} \end{split}$$


# **Interpolating Geometry Matrix**

Invert A to obtain interpolating geometry matrix

$$\mathbf{A}^{-1} = \begin{bmatrix} 1 & 0 & 0 & 0 \\ -5.5 & 9 & -4.5 & 1 \\ 9 & -22.5 & 18 & 4.5 \\ -4.5 & 13.5 & -13.5 & 4.5 \end{bmatrix} \quad \mathbf{c} = A^{-1}\mathbf{p}$$

# Joining Interpolating Segments


- Do not solve degree n for n points
- Divide into overlap sequences of 4 points
- p<sub>0</sub>, p<sub>1</sub>, p<sub>2</sub>, p<sub>3</sub> then p<sub>3</sub>, p<sub>4</sub>, p<sub>5</sub>, p<sub>6</sub>, etc.



- At join points
  - Will be continuous (C<sup>0</sup> continuity)
  - Derivatives will usually not match (no C¹ continuity)


# **Blending Functions**

- Make explicit, how control points contribute
- Simplest example: straight line with control points p<sub>0</sub> and p<sub>3</sub>
- $p(u) = (1 u) p_0 + u p_3$
- $b_0(u) = 1 u$ ,  $b_3(u) = u$



# Blending Polynomials for Interpolation

- Each blending polynomial is a cubic
- Solve (see [Angel, p. 427]):  $p(u) = b_0(u)p_0 + b_1(u)p_1 + b_2(u)p_2 + b_3(u)p_3$




# **Cubic Interpolation Patch**

• Bicubic surface patch with  $4 \times 4$  control points

$$\mathbf{p}(u,v) = \sum_{i=0}^{3} \sum_{k=0}^{3} u^{i} v^{k} \mathbf{c}_{ik}$$

Note: each c<sub>ik</sub> is 3 column vector (48 unknowns)




[Angel, Ch. 10.4.2]

# Outline

- Parametric Representations
- Cubic Polynomial Forms
- Hermite Curves
- Bezier Curves and Surfaces

# Hermite Curves

- Another cubic polynomial curve
- Specify two endpoints and their tangents



#### Deriving the Hermite Form

As before

$$p(0) = p_0 = c_0$$
  
 $p(1) = p_3 = c_0 + c_1 + c_2 + c_3$ 

• Calculate derivative

$$\mathbf{p}'(u) = \begin{bmatrix} \frac{dx}{du} \\ \frac{dy}{du} \\ \frac{dz}{du} \end{bmatrix} = \mathbf{c}_1 + 2u\mathbf{c}_2 + 3u^2\mathbf{c}_3$$

• Yields 
$$p'_0 = p'(0) = c_1$$
  
 $p'_3 = p'(1) = c_1 + 2c_2 + 3c_3$ 

# Summary of Hermite Equations

- Write in matrix form
- Remember p<sub>k</sub> and p'<sub>k</sub> and c<sub>k</sub> are vectors!

$$\begin{bmatrix} \mathbf{p}_0 \\ \mathbf{p}_3 \\ \mathbf{p}_0' \\ \mathbf{p}_3' \end{bmatrix} = \begin{bmatrix} 1 & 0 & 0 & 0 \\ 1 & 1 & 1 & 1 \\ 0 & 1 & 1 & 1 \\ 0 & 1 & 2 & 3 \end{bmatrix} \begin{bmatrix} \mathbf{c}_0 \\ \mathbf{c}_1 \\ \mathbf{c}_2 \\ \mathbf{c}_3 \end{bmatrix}$$

 Let q = [p<sub>0</sub> p<sub>3</sub> p'<sub>0</sub> p'<sub>3</sub>]<sup>T</sup> and invert to find Hermite geometry matrix M<sub>H</sub> satisfying

$$c = M_H q$$

## **Blending Functions**

• Explicit Hermite geometry matrix


$$\mathbf{M}_H = \left[ egin{array}{cccc} 1 & 0 & 0 & 0 \ 0 & 0 & 1 & 0 \ -3 & 3 & -2 & -1 \ 2 & -2 & 1 & 1 \end{array} 
ight]$$

• Blending functions for  $\mathbf{u} = \begin{bmatrix} 1 & u & u^2 & u^3 \end{bmatrix}^T$ 

$$\mathbf{b}(u) = \mathbf{M}_{H}^{T}\mathbf{u} = \begin{bmatrix} 2u^{3} - 3u^{2} + 1\\ -2u^{3} + 3u^{2}\\ u^{3} - 2u^{2} + u\\ u^{3} - u^{2} \end{bmatrix}$$

#### Join Points for Hermite Curves

• Match points and tangents (derivatives)



- Much smoother than point interpolation
- How to obtain the tangents?
- Skip Hermite surface patch
- More widely used: Bezier curves and surfaces

# Parametric Continuity

• Matching endpoints (C<sup>0</sup> parametric continuity)

$$\mathbf{p}(1) = \begin{bmatrix} p_x(1) \\ p_y(1) \\ p_z(1) \end{bmatrix} = \begin{bmatrix} q_x(0) \\ q_y(0) \\ q_z(0) \end{bmatrix} = \mathbf{q}(0)$$

• Matching derivatives (C¹ parametric continuity)


$$\mathbf{p}'(1) = \begin{bmatrix} p_x'(1) \\ p_y'(1) \\ p_z'(1) \end{bmatrix} = \begin{bmatrix} q_x'(0) \\ q_y'(0) \\ q_z'(0) \end{bmatrix} = \mathbf{q}'(0)$$

# Geometric Continuity

• For matching tangents, less is required

$$\mathbf{p}'(1) = \begin{bmatrix} p_x'(1) \\ p_y'(1) \\ p_z'(1) \end{bmatrix} = k \begin{bmatrix} q_x'(0) \\ q_y'(0) \\ q_z'(0) \end{bmatrix} = k\mathbf{q}'(0)$$

- G¹ geometric continuity
- Extends to higher derivatives



# Outline


- Parametric Representations
- Cubic Polynomial Forms
- Hermite Curves
- Bezier Curves and Surfaces

## **Bezier Curves**

- Widely used in computer graphics
- Approximate tangents by using control points

$$p'(0) = 3(p_1 - p_0)$$

$$p'(1) = 3(p_3 - p_2)$$



#### **Equations for Bezier Curves**

- Set up equations for cubic parametric curve
- Recall:

$$p(u) = c_0 + c_1 u + c_2 u^2 + c_3 u^3$$
  

$$p'(u) = c_1 + 2c_2 u + 3c_3 u^2$$

Solve for C<sub>k</sub>

$$p_0 = p(0) = c_0$$

$$p_3 = p(1) = c_0 + c_1 + c_2 + c_3$$

$$p'(0) = 3p_1 - 3p_0 = c_1$$

$$p'(1) = 3p_3 - 3p_2 = c_1 + 2c_2 + 3c_3$$

## **Bezier Geometry Matrix**

Calculate Bezier geometry matrix M<sub>B</sub>

$$\begin{bmatrix} c_0 \\ c_1 \\ c_2 \\ c_3 \end{bmatrix} = M_B \begin{bmatrix} p_0 \\ p_1 \\ p_2 \\ p_3 \end{bmatrix} \text{ so } M_B = \begin{bmatrix} 1 & 0 & 0 & 0 \\ -3 & 3 & 0 & 0 \\ 3 & -6 & 3 & 0 \\ -1 & 3 & -3 & 1 \end{bmatrix}$$

- Have C<sup>0</sup> continuity, not C<sup>1</sup> continuity
- Have C¹ continuity with additional condition

# **Blending Polynomials**

• Determine contribution of each control point

$$\mathbf{b}(u) = \mathbf{M}_B^T \mathbf{u} = \begin{bmatrix} (1-u)^3 \\ 3u(1-u)^2 \\ 3u^2(1-u) \\ u^3 \end{bmatrix}$$


0.4 0.2

0.8 0.6

Smooth blending polynomials

# Convex Hull Property


- Bezier curve contained entirely in convex hull of control points
- Determined choice of tangent coefficient (?)



0.4

#### **Bezier Surface Patches**

• Specify Bezier patch with  $4 \times 4$  control points



Bezier curves along the boundary

$$p(0,0) = p_{00}$$

$$\frac{\partial \mathbf{p}}{\partial u}(0,0) = 3(\mathbf{p}_{10} - \mathbf{p}_{00})$$


$$\frac{\partial \mathbf{p}}{\partial v}(0,0) = 3(\mathbf{p}_{01} - \mathbf{p}_{00})$$

#### **Twist**

• Inner points determine twist at corner

$$\frac{\partial^2 \mathbf{p}}{\partial u \, \partial v}(0,0) = 9(\mathbf{p}_{00} - \mathbf{p}_{01} + p_{10} - p_{11})$$

- Flat means p<sub>00</sub>, p<sub>10</sub>, p<sub>01</sub>, p<sub>11</sub> in one plane
- $(\partial^2 p/\partial u \partial v)(0,0) = 0$



# Summary

- Parametric RepresentationsCubic Polynomial Forms
- Hermite Curves
- Bezier Curves and Surfaces